

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec Cor for 22, 23, 26 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 12 Page 5054)

Set post cor. to secs. 26, 27, 22 and 23, from which
A B.Oak 18" dia. bears S.55°E., 29 lks. dist.
A B.Oak 13" dia. bears N.31°E., 51 lks. dist.
A B.Oak 18" dia. bears N.10°W., 204 lks. dist.
A B.Oak 14" dia. bears S.27°W., 188 lks. dist.

Retracement & Resurvey, GLO, Elmer Strickler, Under Special
Instructions, dated Jan. 22, 1917 (DCSO records, Volume 12
Page 5088)

Intersect the cor. of secs. 22, 23, 26 and 27, which is a
badly decayed post, marked and witnessed as described by the
Surveyor General. At the exact cor. point,
Set a hard limestone, 16x6x6 ins. in the ground marked with
2 notches on S. and E. edges; from which
A B.Oak 20" dia. bears N.31°E., 51 lks. dist. marked
T27S R4W S23 BT. (Orig. BT.)
A B.Oak 20" dia. bears S.47°30'E., 30 lks. dist. marked
T27S R4W S26 BT. (Orig. BT.)
A Fir 18" dia. bears S.56°W., 29 lks. dist. marked
T 27 S R 4 W S 27 BT (Orig. BT.)
A Fir 16" dia. bears N.58°15'W., 12 lks. dist. marked
T27S R4W S22 BT. (Orig. BT.)

James W. Byron, Deputy - Milo Godfrey; S.A. Bilow -
December 31, 1958 - C.S. File 49/130-2

Found - Stone as recorded at corner. I chisel +, 4" high on
NE face.
Orig. 16" now 20" Fir N.58¼°W., 7.9 ft. Stump only.
Orig. 18" now 22" Fir down, find good scribing.
Orig. 20" now 24" B.Oak S.47½°E., 19.8 ft. shows
good scars, I do not open.
Orig. 20" now 24" Oak, down. I do not open.
New BTs - 12" R.Fir bears N.68°E., 11.6 ft. scribed S23 T27S
R4W CS BT.
6" Cedar bears N.66°W., 20.4 ft. scribed S22 CS BT.
6" Cedar bears S.13°E., 10.0 ft. scribed S26 CS BT.
22" R.Fir bears S.60°W., 56.6 ft. scribed S27 T27S
R4W CS BT.

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec Cor for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone
Oct. and Nov. 1963 - C.S. File 53/33-32

Found - Rock mound at corner, no marks found on any of them.
9" I.Cedar N.66°W., 20.4 ft. scribing visible on not
completely healed scar.
9" I.Cedar S.13°E., 10.0 ft., scribing visible on
scar.
24" D.Fir S.60°W., 56.6 ft. scar pitched over,
scribing visible.
(All three of these trees are alive & in good condition)
12" Fir N.68°E., 11.6 ft. is broken off 6 ft. above
ground, all scribing visible.
B.Oak S.47½°E., 19.8 ft., still alive & standing,
but in poor condition.

Set brass cap (in place of rock) mkd: County Surveyors Office
T 27 S R 4 W S 22 | S 23 1963
S 27 | S 26

Pile rocks around cap.
New BT - 6" I.Cedar N.71°E., 37.4 ft. mkd: T27S R4W S23 CSBT
Corner lies 3 ft. North of E & W fence line.

Found and used in BLM resurvey, G. Baughman, Contract #52500-
CT5-1116, (DCSO records, Vol. 39, Pages 15792-93)

Found OK, October 1994 by Dolan - M119-44

Found OK by N. Hibbs, Dec. 1999 - P. Plat 2000-0007 A & B