

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 and 36 only

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - Addison R. Flint, Contract #56 dated March, 1855  
(DCSO Records, Volume 12 Page 5048)

-----  
Set sec. post, from which  
    A Maple, 5" dia. bears N.25°E., 20 lks. dist.  
    A Fir 10" dia. bears S.80°E., 22 lks dist.  
    A Fir 6" dia. bears S.57°W., 33 lks. dist.  
    A Fir 24" dia. bears N.58°W., 42 lks. dist.

Exteriors as surveyed by W.H. Byars, Under contract #376  
dated January 22, 1881 (DCSO Records, Volume 12 Page 5081)

-----  
Sec. Cor. to secs. 2, 1, 35, and 36. Set new post as per  
instructions, bearing trees all standing (as per Flint, 1855)

James W. Byron, Deputy Co. Surveyor; Dale McFarland; Jim  
Powell - Sept. 14, 1961 - C.S. File 49/67-33

-----  
Found - Orig. 6" now 30" R.Fir S.57°W., 21.8 ft.  
          Orig. 24" now 30" R.Fir N.58°W., 27.7 ft. shows  
          good bark scribing.  
          NE & SE BTs, now 30" Firs, show good bark scribing.  
          Now down slope about 50 ft. Stump holes check  
          bearing & distances. NE BT not a Maple.  
Set brass cap mkd: County Surveyors S 35|S 36 T27S  
  Office, 1961                   T28S R4W  
New BT - 16" R.Fir bears N.47°E., 57.3 ft. scribed S36 T27S  
  R4W CS BT.

Found OK by D.Edwards, 4/2001 - M138-8 & 65/34-6A & B  
Fd. Ok by D. Edwards, 7/2010 - C.S. File 65/69-46  
Fd as per record by D. Edwards, 10/2022 - C.S. File 65/110-7