

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO Subdivisions of T.27-4 by Elmer F. Strickler under Special Instructions dated Jan.22, 1917 (DCSO records Volume 12 Page 5093)

Set an Iron post, 3 ft. long, 1" dia. 26" in the ground for 1/4 sec. cor., with brass cap marked: S13

1/4 S24
1917 from which

A Hemlock 10" dia. bears N.50°W., 36 lks. dist. marked 1/4 S13 BT.

A Cedar 17" dia. bears S.70°W., 46 lks. dist. marked 1/4 S 24 BT.

This cor. is 150 ft. below the top of the spur; from this cor. Mrs. J. Cockelreas' house bears N.7°E.

Milo E. Godfrey, Deputy Co. Surveyor - Stoffel and Stone October 1963 - C.S. File 53/33-18

Found - Iron pipe with brass cap set in 1917 survey.
28" R.Cedar S.70°W., 30.4 ft., good scribing visible on previously opened blaze "1/4 S24 BT", in good condition.

Rotten remnants only of Hemlock stump N.50°W., 23.8 ft., no marks.

New BT - 14" R.Cedar N.78 1/2°E., 22.7 ft. mkd. 1/4 S13 CS BT.

Found OK, Burton Holt, March 1982, M 91-37

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1925, surveyed June/Dec. 2000 - (DCSO rec. Vol. 53 Page(s) 20542-3)

The 1/4 sec. cor. of secs. 13 & 24, perpetuated by Godfrey, Douglas County Deputy Surveyor, in 1963, monumented with an iron post, 1 in. dia., firmly set, projecting 16" above ground, with brass cap mkd. 1/4 S 13

S 24
1917

from which the remains of an original bearing tree

A cedar snag, 24" dia., bears S.70°W., 30.4 ft., with scribe marks 1/4 S24 T visible on open blaze.

and remains of a bearing tree mkd. by Godfrey

A sawed cedar stump, 27" dia., bears N.78 1/2°E., 22.7 ft., with a healed blaze.

and two new bearing trees

A fir, 18" dia., bears S.43 1/2°W., 10.8 ft., mkd. 1/4 S24 BT.

continued next page

