

PRIMARY CORNER DESCRIPTION INTERIOR I. COR. DLC #39

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint - Cont. #28 - commenced July 1854

Set - Post from which
W. oak 32" bears S.35°E., 190 lks.
B. Oak 25" bears N.89°W., 270 lks.

A. Boyer, Doug. Co. Surveyors Office - Wit. Ted Shellabarger
Dec., 1938 - Vol. 4 Pg. 57

On E. side of S. Main St. near Mosher, set from remains of BT
which is S.35°E., 190 lks. from corner and is original White
Oak BT as certified to in a written, filed statement by Mr.
E.L. Giles in V. E. .
Set - A 1" steel auto axle from which:
The street monument just south of 331 S. Main St.
bears S.50°W., 97 ft.
A cross on curb at about prop. line between 315 and
331 S. Main St. bears N.41°W., 22.5 ft.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 1/13/1999 - C.S. File 66/8-1

Found: Corner monument not found. Location of corner falls
within new concrete of a private driveway
No orig. BT"s found.
Cross in curb from 1938 renewal not found.
Street monument under access cover in Main St.
bears S.50°W., 97.0 ft. 1938 DCSO
The following are computed monument ties using a combination
of recorded surveys (M11-19, 1946); (M17-41, 1949) and
(M14-19, 1959).
½" I.P. found 3" below ground, bears N.7°W., 11.1
ft. (agrees w/computed rec.)
¾" I.R. slightly bent, protrudes 1" above ground,
plumb position bears N.88½°W., 74.2 ft. (agrees
w/computed record).
"X" chiseled in driveway, bears S.63 ¾°W., 113.7
ft. (agrees with computed record).
SET: A 3" dia. brass cap is set flush in concrete
driveway.
DOUGLAS COUNTY SURVEYORS OFFICE
T27S R
DLC 5
39 W
1999
North west corner of house at 953 Main Sst. bears
S.26°E., 23.0 ft. (block corner of wall)