

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - W. Penby - V. Perron - 3/71 -
C.S. File 53/384

Corner destroyed by clearing of sheep pasture.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 4/93 - C.S. File 64/43-32

Corner looked for and not found.