

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec. Cor. 24 & 25; S. 19 & 30, T27-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - James E. Freeman Contract #1 dated May, 1851 ----- Set post, cor. of secs. 19, 24, 25 & 30, from which A B.Oak, 28" dia. bears S.79 3/4°E., 556 lks. dist. A B.Oak, 15" dia. bears S.21°30'W., 993 lks. dist. Make trench as per instructions.</p>
<p>Ben B. Irving, County Surveyor For California Oregon Power Company - April, 1953 - C.S. 45/150 ----- Set - 1" brass cap 6" below ground, from which 10d nail in top of anchor post bears N.40°36'E., 31.22 ft. 10d nail in anchor post bears S.41°41'E., 12.53 (28.0 ft. M.E.G.) Metal 6 on C.O.P.C.O. pole # B 6125 bears S.80°52'W., 12.53 ft.</p>
<p>Found OK, Don Bentz, August, 1987 - M 101 - 26</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 11/16/93 - C.S. File 64/50-8 Found - 2½" dia., DCSO brass cap on an iron pipe, 12" below road surface. PPL power pole #B6125, bears S.82½°W., 13.2' to center of power pole. (Rec. S.80°52'W., 12.53', dist. fits well outside edge of pole) 1953 BBI. Both anchor post recorded in 1953 BBI renewal are gone. New - 5/8" iron rod, 3" below road surface, bears S.63°E., 22.5'. 11" dia., D.Fir, at Northwest corner of property at 602 O.C. Browning Rd., single small low blaze "S19 BT", bears N.11½°E., 115.0'. PK nail in top center of a 13" dia., 5½' high corner post bears S.42 3/4°E., 29.6'. See sketch in C.S. File 64/50.</p>
<p>Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 3/17/2008 - C.S. File 67/25-34 ----- Fd. ok as per 1993 DCSO Record.</p>