

PRIMARY CORNER DESCRIPTION Standard Cor. Secs. 32 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Samuel C. Flint, Under Contract #473, dated June 5, 1883 (DCSO Records Vol. 24 Page(s) 10141)

Set post, 50x4" firmly in the ground for stan. cor. to secs. 32 & 33, marked S C T 27 S R 6 E on N, S 33 on E and S 32 on W faces, with 4 notches on E and 2 on W faces, from which
A pine, 16" dia., bears N.25°E., 62 lks., mkd: T27S R6E S33 BT.
A pine, 10" dia., bears N.50°W., 38 lks., mkd: T27S R6E S32 BT.
A pine, 12" dia., bears S.75°W., 17 lks., mkd: S BT.
The land around the lake is usually good and affords abundance of good grass.

Douglas Co. Surveyors Office - Clell Goodwin - Lenora Ladig - 9/17/1975 - C.S. File 57/36-6

Found - 14" Pine blazed, scarred over and reopened several years ago showing faint scribe "S BT" on North face from which a 1" IP bears N.17°E., 16.0 ft.
Set - Brass cap on 1½"x30" IP stamped
DOUGLAS CO. SURVEYOR T27S
1975 R 6E
S 32|S 33
T28S

From which
A 14" Pine (orig. 12" Pine) bears S.7°W., 11.2 ft.
The remains of a rotten stump (possible orig. 10" Pine bears N.57°W., 23.6 ft.
An unrecorded 1" IP, projecting 24" above ground and apparently used for corner bears N.23°W. 13.1 ft.
New - A 16" Pine scribed "T27S R6E S32 CS BT" in a double blaze bears N.26°W., 49.3 ft.
A 12" Pine scribed "T27S R6E S33 CS BT" in a double blaze bears N.28°E., 64.9 ft.
A thorough search of the area shows no other identifiable remains of the corner or accessories. Compass decl. 20° East

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 10/14/1998 - C.S. File 66/4-4

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 6" above ground, properly marked. 1975
16" dia., now badly burnt stump found near record "N.25°E., 40.9 ft". OBT
No evidence of Orig. NW BT found.

continued next page

TOWNSHIP 27 RANGE 06E POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard Cor. Secs. 32 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

	12" dia., now fallen down 13" dia., Lodge Pole Pine with a previously opened blaze scribing visible "S BT" bears S.75°W., 11.2 ft. (Agrees w/rec) OBT
	16" now 14" dia., Lodge Pole Pine with an unhealed double blaze, scribing visible "T27S R6E S32 CS BT" bears N.26°W., 49.3 ft. (Agrees w/rec.) 1975
	12" now 12" dia., Lodge Pole Pine with an unhealed double blaze, scribing visible "T27S R6E S32 CS BT" bears N.28°E., 64.9 ft. (Agrees w/rec.) 1975
New BTs-	9" dia., Lodge Pole Pine double blazed and scribed "T27S R6E S32 CS BT" bears N.53°W., 22.8 ft.
	6" dia., Lodge Pole Pine double blazed and scribed "SCS BT" bears South 16.9 ft.