

PRIMARY CORNER DESCRIPTION NW Cor. LaPoint DLC #64

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Contract #28 dated April, 1854  
-----

Set a post N W Corner of C 64, from which  
A B.Oak 15" dia. bears N.48°W., 24 lks.  
A B.Oak 20" dia. bears N.55°E., 55 lks.  
A B.Oak 10" dia. bears S.76°E., 52 lks.

N.E. Richardson, Deputy Co. Surveyor, M.E. Godfrey; L.S.  
Kershner - For: Short & York - 8/7/1947 - C.S. 39/98 M 18 - 49  
-----

Set 5/8" x 30" iron rod with a mound of rock.  
Remarked three O.B.T's.

Doug. Co. Surveyor Office - R.B. Kimberling; M.W. Cline  
July 5, 1977 - C.S. File 59/38-2  
-----

Found - 5/8" x 30" I.R. in mound of stone. (1947)  
An Oak stump, 15" now 26" bears N.48°W., 15.8 ft.  
with blaze but center rotted and burned.  
An Oak stump, 20" now 42" bears N.55°E., 36.3 ft.  
with possible healed blaze, center rotted  
away. Location of third BT is in relocated  
highway.  
Set - Brass cap on 1" x 30" I.P. in mound of stone 30"  
dia. 2.0 ft. high mkd. "County Surveyors  
Office" T27S

N.W. Cor.  
R 6 W  
1977

Set 5/8" x 30" I.R. 0.1 ft. west of BC flush with top.  
New BTs - A 14" B.Oak bears S.4°E., 87.0 ft. double blazed  
& scribed "DLC 64 T27S R6W CS BT".  
A 15" madrone bears N.42°E., 64.5 ft. double blazed  
and scribed "S6 T27S R6W CS BT"  
Note - Corner is on North bank of Melrose Rd. at #955 mailbox

Douglas County Surveyors Office - Steve Flause; Shawn Means  
March 25, 1980 - C.S. File 61/6-15  
-----

Found - 5/8" I.R. lying loose on surface of ground and a  
scattered mound of stone (1947). A brass cap  
from 1977 is missing.  
An orig. 15" B.Oak now a 26" stump bears N.48°W.,  
15.8 ft some evidence of a blaze but center is  
rotted & burned, no scribing evident.

Continued next page

PRIMARY CORNER DESCRIPTION NW Cor. LaPoint DLC #64

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

An orig. 20" B.Oak now 42" stump bears N.55°E., 36.3 ft some evidence of possible healed blaze, center of stump is rotted & burned, no scribing evident. Above distances were measured from orig. face diam. of stumps to center of remaining evidence of mound of stone (See renewal procedure)  
A 14" now a 15" B.Oak bears S.5°E., 87.0 ft. (Rec. S.4°E., 87.0 ft.) with a double blaze scribed "DLC 64 T27S R6W CS BT" and partially healed.  
A 15" now 16" madrone bears N.42°E., 64. ft. with a double blaze scribed "S6 T27S R6W CS BT" and partially healed.

Note - After checking record distances from center of root crowns of orig. BT stumps & finding bearings to be off, it is assumed orig. distances were made as face measurements: checking this assumption by measuring & intersecting orig. record distances from orig. 10" & 20" BT diameters, it is found that bearings to BTs are of record & corner location falls near center of remains of mound of stone from 1947; This location is accepted as the corner position.

Set - A Doug. Co. Surveyors Office bronze drill cap in sandstone bed-rock over which we place the 5/8" x 30" I.R. in a mound of stone measuring approx. 2.5 ft. tall. Cap is mkd. T27S NW DLC 64 R6W 1980.

New BT tags are placed on OBT stumps. Corner is on North bank of Melrose Road #13 at Route #955.