

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set 1/4 Sec. post, from which
 A Fir, 10" dia. bears S.17°W., 50 lks. dist.
 An Ash, 14" dia. bears S.67°E., 97 lks. dist.

M.B. Germond Co. Sur., Jan. & Feb. 1917 (Possible sources
C.S. 4/25; F.B. 44 Pg. 31-34; F.B. 69 Pg. 65)

One old bearing tree in evidence. New corner is pipe 1" x 24"
and stone 6" x 8" x 12" from which:
 A Cedar 14" dia. bears N.25°55'E., 16 lks. dist.
 A Fir 28" dia. bears N.78°30'W., 11 lks. dist. Center of
 tree.

James W. Byron, Deputy County Surveyor - Milo Godfrey; Clete
Putnam - January, 1961 - C.S. 49/79-12

Found - Iron pipe & rock called for by Germond.
 Rotten Fir snag N.78½°W., 7.3 ft.
 Cedar N.26°E., 10.6 ft. is uprooted & down.
Set - Brass cap mkd. County Surveyor's Office, 1961
 alongside rock & pipe - 1/4 S23/S24 T27S R6W
New BTs - 6" B.Oak N.79°E., 40.6 ft. Mkd. 1/4 S24 CS BT.
 10" madrone N.10°W., 62.0 ft. mkd. 1/4 S23 CS BT.