

PRIMARY CORNER DESCRIPTION Sec Cor for 19, 20, 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 13 Page 5263)</p> <p>-----</p> <p>Set post, cor. secs. 19, 20, 30 and 29, from which</p> <ul style="list-style-type: none"><li>An Oak 24" dia., bears N.77°E., 197 lks. dist.</li><li>An Oak 20" dia., bears S.59°E., 40 lks. dist.</li><li>An Oak 24" dia., bears S.15°W., 12 lks. dist.</li><li>An Oak 20" dia., bears N.45°W., 100 lks. dist.</li></ul>
<p>Original - A.R. &amp; L.C. Flint, under Contract #392 dated May 26, 1881 - (DCSO records, Vol. 13 Pages 5268)</p> <p>-----</p> <p>Post gone - made new post 4" dia., 3½ ft. long, and set firmly in the ground, from which</p> <ul style="list-style-type: none"><li>An Ash 24" dia., bears N.77°E., 197 lks. dist.</li><li>An Ash 20" dia., bears S.59°E., 40 lks. dist.</li><li>An Ash 24" dia., bears S.15°W., 12 lks. dist.</li><li>An Ash 20" dia., bears N.45°W., 100 lks. dist.</li></ul>
<p>Doug. County Surveyors Office - James Byron, Deputy - M. Godfrey; S. Bilow - April 1958 - C.S. File 49/79-48</p> <p>-----</p> <p>Found - Three of original BTs.</p> <ul style="list-style-type: none"><li>Orig. 20" now 42" B.Oak, old face exposed, good scribing visible "R8W S." (I confirmed that Byron's field notes says "R8W S") V.L.</li><li>Orig. 24" now 40" S.15°W., 7.9 ft. badly burned snag, face gone.</li><li>Orig. 20" now 36" Oak snag S.59°E., 26.4 ft., shows old face rotted.</li></ul> <p>Also find hole for original NE BT.</p> <p>All BTs check for bearing and distance.</p> <p>Fence corner bears N.55°W., 48.6 ft.</p> <p>Set Brass cap at cor. mkd: T27S R7W County Surveyors <u>S19 S20</u> Office, 1958 <u>S30 S29</u></p> <p>New BTs - 18" R.Fir bears S.62°W., 36.2 ft. scribed T27S R7W S30 CS BT.</p> <ul style="list-style-type: none"><li>10" Laurel bears N.25°E., 54.7 ft. scribed T27S R7W S20 CS BT.</li><li>42" B.Oak (orig.) N.45°W., 66.0 ft. scribed T27S R7W S19 CS BT.</li></ul> <p>No live trees near in SE quadrant.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/28/1999 - C.S. File 66/8-12</p> <p>-----</p> <p>Found - 2½" brass cap on a 1½" o.d. iron pipe protrudes 14" above ground. 1958 continued next page</p>

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Cor Secs 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

24" now rotted oak remains at record "S.15°W., 7.9 ft." OBT  
20" now 49" dia. B.Oak with a healed blaze, bears "N.45°W., 66.0" OBT  
No other OBTs found.  
18" now rotted to ground D.Fir and root hole, at record "S.62°W., 36.2 ft. 1958  
10" now 22" dia. Madrone with a fully healed blaze, bears N.25°E., 54.7 ft. 1958.  
New - Doubled trunked Madrone bark scribed "CS T27S R7W S29 BT" on an 8" dia. westerly trunk, bears S.75°E., 10.0 ft.  
19" dia., Madrone double blazed and scribed "T27S R7W S30 CS BT" bears S.63½°W., 50.3 ft.

Found OK by T. Hostetter, May 2000 - M135-4  
Fd. BC by Mark Heimbürger, 5/2008 - M155-67