

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 208100

PRIMARY CORNER DESCRIPTION Angle Point So Bdy Sec 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Page 5231)

Set post, cor. of secs. 5 and 6, from which
A Fir 30" dia., bears S.71°W., 22 lks. dist.
A Maple 12" dia., bears S.44°E., 42 lks. dist.

GLO survey by Fred Mensch, under Contract #109 dated 1924 (DCSO records, Vol. 14 page 5850)

Intersect the cor. established by Hathorn for standard cor. of secs. 5 & 6, located by measurement from the original bearing trees. The SW tree has been cut down, marks legible on the stump. The SE tree shows old blazes, marks overgrown. At the exact cor. point, Set an iron post, 3' long, 1" dia., 28" in the ground, for angle point, with brass cap mkd: AP 1924
from which
(old bearing tree), A Maple, 14" dia., bears S.44°E., 42 lks. dist., re-marked AP BT.
(New bearing tree) A Fir 36" dia., bears S.46°W., 72 lks. dist., marked AP BT.

Doug. County Surveyors Office - James W. Byron, Deputy, Milo Godfrey; Clete Putnam - Feb. 1961 - CS File 49/79-32

(Renew angle point, S.38°21'W., 7.39 chs. from NE corner Sec. 6 of T28-7)
Found - Brass cap. SW BT, now stump. SE BT shows scar.
New BTs - 20" Myrtle bears N.63½°E., 40.0 ft. scribed AP CSBT.
6" W.Fir N.55½°W., 42.6 ft. scribed AP CS BT.

Fd. Ok by D.Edwards, 11/96, M 126-13.
Fd. OK by McLind, surveyed Dec.'96 thru Feb.'98 - M 128-40

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 5/28/1998 - C.S. File 66/2-41

Found - 2½" dia., brass cap on a 1" O.D. iron pipe, protrudes 6" above ground, properly mkd. 1924
12" now rotted Maple found at record bearing S.44°E., 27.7 ft." Note newer Maples are growing from this OBT.
(Cont. next page)

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 208100

PRIMARY CORNER DESCRIPTION Angle Point South Bdy Sec 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

6" now badly rotted W.Fir stump with axe mark, no scribing visible, near record "N.55½°W., 42.6 ft." 1961

20" now 22" dia., Myrtle with a fully healed double blaze, bears N.63½°E., 40.0'. Agrees with rec. 1961

36" now 32" dia., 5 ft. high D.Fir stump with a fully healed single blaze, bears S.46°W., 47.5'. (Agrees with rec. dist. is to blaze) 1924

New BTs- 12" dia., Maple double blazed and scribed "AP S32 CS BT" bears S.44°E., 26.1'.

6" dia., Maple double blazed and scribed "AP S32 CS BT" bears N.32½°W., 7.2'.

Corner lies approx. 50' south of a creek on a steep North slope.