

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 & 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Page 5256)

-----  
Set post, cor. secs. 16, 17, 20 and 21, from which  
A B.Oak 30" dia., bears N.50°W., 266 lks. dist.  
A B.Oak 18" dia., bears S.53°W., 273 lks. dist.  
A B.Oak 18" dia., bears S.51°E., 316 lks. dist.  
A W.oak 36" dia., bears N.45°E., 327 lks. dist.

-----  
F.C. Frear; Stark and W.L. Daniels for: Waite Land for W.E. St. John - October 14-15, 1919 - Field Book 47 Page 14 (Also "old" Corner book, Page 97)

-----  
Reestablished from original bearing trees, all standing by setting 1½" x 48" Iron pipe and remarking the BTs.

-----  
Doug. County Surveyors Office - James W. Byron, Deputy Milo Godfrey; Clete Putnam - June 20, 1960 - C.S. 49/79-53

-----  
Found - Orig. 36" now 46" W.Oak snag N.45°E., 215.8 ft. I open & find good reverse scribing "BT".  
Orig. 18" now 40" B.Oak snag S.51°E., 208.6 ft. I do not open.  
Orig. 18" now down Oak and mostly rotted, S.53°W., 180.2 ft.  
No trace of orig. NW BT.  
1¼" Iron pipe, top broken, at corner.  
Set Brass cap at cor. mkd: County Surveyors Office S17|S18 T27S  
Office, 1960 S20|S21 R7W  
New BTs - 6" R.Fir bears N.41°W., 31.0 ft. scribed S17 CSBT.  
8" R.Fir bears S.51°W., 51.5 ft. scribed S20 T27S R7W CS BT.  
21" W.Oak bears S.64°E., 22.5 ft. scribed S21 T27S R7W CS BT.  
6" R.Fir bears N.81°E., 22.4 ft. scribed S16 CS BT.

-----  
Marc Brittain - 4/2011 - M157-40 A&B

-----  
Condition report  
Found 2½" brass cap mon. (+1.0' AGL)  
18" Fir stump bears N.83°E., 22.2'  
22" W.Oak bears S.69°E., 20.4'  
16" Fir stump bears S.49°W., 51.4'

-----  
Fd. by M. Brittain, 11/2012 - M165-25