

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Page 5242)

Set post, cor. secs. 22, 23, 26 and 27, from which
A B.Oak 12" dia., bears N.42°W., 83 lks. dist.
A B.Oak 10" dia., bears N.20°E., 42 lks. dist.
A B.Oak 10" dia., bears S.75°W., 108 lks. dist.
A B.Oak 10" dia., bears S.11°E., 91 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy
Milo Godfrey; Clete Putnam - Nov. 1960 C.S. File 49/79-56

Found - Orig. 10" now 16 Oak snag, N.20°E., 27.7 ft.
We open & find good reverse scribe "23R".
Orig. 12" now 24", down Oak, checks bearing &
dist. for NW BT.
Orig. SW BT gone. Orig. SE BT gone.
Set Brass cap at cor. mkd: County Surveyors S22|S23 T27S
Office, 1960 S27|S26 R7W
New BTs - 9" Cedar bears N.65°E., 11.7 ft. scribed S23
T27S R7W CS BT.
14" Pine bears S.25°W., 6.3 ft. scribed S27
T27S R7W CS BT.
10" Cedar bears S.76°E., 27.5 ft. scribed S26
T27S R7W CS BT.
14" R.Fir bears N.13°W., 35.0 ft. scribed
S22 T27S R7W CS BT.

BLM dependent resurvey by Philip G. Griffin, Cadastral
Surveyor, under Group # 1529, surveyed April/July 1990
(DCSO records Vol. 50 Page(s) 19137)

Cor. remonumented by the Douglas County Surveyor's Office
in 1960, with an iron post, 1½ ins. diam., loosely set,
projecting 26" above ground at the corner of wire fences,
extending N., S., E., and W., with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 27 S R 7 W

S 22 | S 23

S 27 | S 26

1960

from which the remains of an original bearing tree

A root hole, bears N. 42° W., 83 lks. dist.

(Cont. Next Page)

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 & 27

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

and the remains of the bearing trees mkd. by the Douglas County Surveyor

A rotted pine stump, 16 ins. diam., bears S. 25° W., 10 lks. dist., no marks visible.

A Douglas fir, 17 ins. diam., bears N. 15° W., 53 lks. dist., with healed double blaze.

The remains of another bearing tree,

A cedar log, 10 ins. diam., with scribe marks R7W S23 CS is down and displaced.

and new bearing trees

A cedar, 10 ins. diam., bears N. 38° E., 86 lks. dist., mkd. T27S R7W S23 BT.

A cedar, 18 ins. diam., bears S. 53° E., 59 lks. dist., mkd. T27S R7W S26 BT.

A cedar, 9 ins. diam., bears S. 87° W., 51 lks. dist., mkd. T27S R7W S27 BT.

Reset the county monument firmly alongside the fence corner, projecting 18 ins. above ground.