

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Page 5235)

Set ¼ sec. post, from which
 A B.Oak 15" dia., bears S.81°E., 28 lks. dist.
 A B.Oak 10" dia., bears S.47°W., 12 lks. dist.

J.W. Cole - For: Mr. Vashow - April 28, 1924 - Volume 3
Page 177; Field Book 31 Page 45; & "Old" Cor. book Pg. 97

I renewed this corner from the original tree, S.47°W., 12 lks. which I chopped open and found scribe mark.
I set a cedar post and a mound of rock.
I marked the following trees:
 A W.Oak 10" dia., bears N.68°00'W., 30 ft.
 A W.Oak 5" dia., bears N.75°30'E., 37 ft.
I also set a steel auto axle at the corner.

Doug. County Surveyors Office - John Powell and crew
November 24, 1970 - C.S. File 54/23-36

Found - Steel Axle shaft at ¼ cor., which falls in N-S & E fence corner.
Also found BTs to be turned around.
Rec. 10" W.Oak N.68°W., 30.0 ft. found 5" W.Oak N.68°E., 37.0 ft.
Rec. 5" W.Oak N.75½°E., 37.0 ft., found 10" W.Oak N.75½°W., 30.0 ft., scribe visible "¼S" & other marks partly grown over.
Original 10" Oak, down, rotten, S.47°W., 7.9 ft., scribe found 2 reverse scribings.
Trees tagged OK.

Fd. Steel Axle shaft & 2 BTs, by B.Rogers, June 1995, 1995-0069
Fd. Axle, D.Edwards, May 1997 - M 127-24
Fd. axle, N. Hibbs, Aug. 2001 - part. plat 2001-0081 A&B
Fd. Ok by K. DeGroot, Oct. 2003 - 2003-0083