

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION (WC) Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Pages 5236-37)

Set post, cor. secs. 13, 14, 23 and 24 from which
A B.Oak 12" dia., bears N.75°W., 101 lks. dist.
A B.Oak 20" dia., bears N.57°E., 15 lks. dist.
A B.Oak 20" dia., bears S.35°E., 23 lks. dist.
A B.Oak 15" dia., bears S.20°W., 46 lks. dist.

L.G. Hicks - May 1914 - M 33-41 - C.S. 19/30 A & B - F.B. 66
Pages 12-33

Fd (?) - 4" Oak Post
24" B.Oak S.33½°E., 15.0'.
24" B.Oak N.56°E., 9.5'.
18" B.Oak N.74°W., 6.7'.
24" B.Oak S.17½°W., 30.0'.
Set (?) - Iron pin

Doug. County Surveyors Office - James Byron, Deputy Milo Godfrey; Clete Putnam - Nov. 21, 1960 - C.S. File 49/79 -61

Found - Oak tree, down & rotted, N.75°W., 66.7 ft. Good reverse scribing "BT".
Oak tree, down in creek, N.57°E., 9.9 ft. Good reverse scribing "BT".
Rotted Oak stump in place, S.35°E., 15.2 ft., no scribing found.
Rotted Oak stump in place, S.20°W., 30.4 ft., no scribing found.

Position for corner falls in Creek & directly in N & S fence line. Set WITNESS CORNER - Iron pipe with brass cap marked:

10' North to Corner County Surveyors S14|S13 T27S R7W
Office 1960 S23|S24

New BTs - 10" P.Pine S.60°W. 31.0 ft. mkd. T27S R7W WCS23 CSBT
9" W.Oak N.23°W. 51.4 ft. mkd. T27S R7W WC S14 CS BT
6" W.Oak N.37°E., 33.2 ft. mkd. T27S WC S13 CSBT.
7" D.Fir S.60°E., 7.7 ft. mkd. T27S R7W WC CS BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 10/24/2002 - C.S. File 66/34-42

Found - 1960 DCSO brass cap/iron pipe in N-S fence line protrudes 12" out of ground. Monument is a Wit. Cor. True corner 10 ft. North.

continued next page

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION (WC) Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

10" now rotted tipped out of ground Pine stump.
Scribing found "WCS23CS" roothole bears S.60°W.,
31.0 ft. (1960)

9" now 14" dia., W.Oak with a fully healed double
blaze, bears N.25°W., 50.3 ft., (rec. N.23°W.,
51.4 ft.) (1960)

6" now 14" dia., W.Oak with a fully healed double
blaze bears N.37°E., 32.6 ft. (rec. N.37°E., 33.2
ft.) (1960)

7" now 15" dia., D.Fir with a fully healed double
blaze, bears S.60°E., 7.7 ft. (1960)

No OBTs found.

New - 14" dia., Madrone double blazed & scribed "T27S R7W
WC S23 CS BT" bears N.78½°W., 28.2 ft.
Compass decl. 17½°E.