

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 30 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5288)

-----  
A Hemlock 30" dia., for 1/4 sec. cor. I mark 1/4 S on W. side, from which  
A Yew 12" dia., bears N.50°E., 30 lks. dist. mkd. 1/4 S BT  
A Maple 6" dia., bears N.6°W., 40 lks. dist. mkd. 1/4 S BT

Survey by Robert C. Adamek - For: Weyerhaeuser Co. - Nov. 1975 - C.S. File 58/76 and M 58-54

-----  
Found - A BLM reference point established before the orig. BTs and corner were obliterated. Reference: BLM corner notes 27-8 A-19. A Yew which bears N.50°E, 19,8 ft.  
Set 3/4" Iron pipe, from which  
12" Hemlock bears S.10°E., 22.5 ft.  
40" D.Fir stump bears N.11°W., 28.1 ft.

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #903, surveyed March 1976 (DCSO records Vol. 39 Page(s) 15713)

-----  
The 1/4 sec. cor., perpetuated and recorded by Adamek in 1975, monumented with an iron pipe, 3/4" dia., firmly set, projecting 6" above ground, and in the root hole of the original corner tree, a Hemlock 36" dia., lying downhill, no marks visible on healed blaze, from which the remains of the original bearing trees:  
A Yew 17" dia., bears N.50°E., 30 lks. dist., with axe marks visible on open blaze.  
and the remains of bearing trees mkd. by Adamek  
A Hemlock 12" dia., bears S.10°E., 34 lks. dist. mkd. 1/4 S30 BT.  
A sawed Fir stump 40" dia., bears N.11°W., 42 1/2 lks. dist. with a galv. nail with "W" embossed on head, at base.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 27 S  
R 9 W R 8 W  
1/4 S 30  
1976