

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 100278

PRIMARY CORNER DESCRIPTION C C for Secs. 24 & 25 only, T27-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Samuel W. Lackland, Deputy Surveyor, under Contract #660, surveyed June/Aug. 1897 - C.S. File 64/76-3

At point of intersection (135 lks. S. of cor. to 19 & 30), Set a sandstone 18x10x4 ins., 12" in the ground for closing cor. of secs. 24 and 25, marked C C on W. face, with 2 grooves on S. and 4 grooves on N. face, from which

A Fir 30" dia., bears S.51°W., 27 lks. dist. mkd. T27S R9W S25 BT.

A Fir 36" dia., bears N.85°W., 93 lks. dist. mkd. T27S R9W S24 BT.

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #903, Surveyed Marcy 1976 - (DCSO records Vol. 39 Page(s) 15716)

True point for the closing cor. of secs. 24 and 25, at intersection with the W. bdy. of T27S R8W.

Set an iron post 28" long, 2½" dia., 22" in the ground, with brass cap mkd.

	T 27 S	R 27 S
CC	S 24	R 8 W
	S 25	S 30
	R 9 W	
	1976	

from which

A Fir 44" dia., bears S.5°W., 18 lks. dist., mkd. T27S R9W S25 CC BT. (An original BT)

A Fir 47" dia., bears N.83°W., 72 lks. dist., with healed blaze. (An orig. BT)

No other suitable trees available within limits.

Tony Hostetter - For: Weyerhaeuser - June 2014 - C.S. File 65/86-9

Found - 1976 BLM brass cap as described DCSO Vol. 39, pg. 15716 From which:

1976 BLM brass cap, sections 19 & 30, T27S R8W bears N.01°10'W., 101.32 ft.

New BTs- 15" fir, scribed "S24 SE BT", BT tag, bears N.41°E., 14.0 feet to spike.

9" fir, scribed "S24 SE BT", BT tag, bears N.80°W., 4.4 feet to spike.

10" fir, scribed "S24 SE BT", BT tag, bears N.41°W., 12.8 ft to spike.