

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5340)

Set a yew post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N face; from which
A cedar, 30" dia., bears N.38°W., 9 lks., mkd: ¼ S BT.
A cedar, 36" dia., bears S.18°30'W., 14 lks., mkd: ¼ S BT.

Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-12

Per note on file:
"The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument." July 1983 V. Laugen - This information added to the corner report on 2/11/2008. DCSO
From corner point: 35" cedar bears N.21½°E., 108. ft.
52" fir stump S.04½°W., 41.7 ft.