

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5352)

Set yew post, 15 lks., form right bank of river, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S. on N face, from which

A fir, 40" dia., bears N.48°E., 48 lks., mkd: ¼ S BT.

A fir, 30" dia., bears N.41°30'W., 61 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - W. Penley - J. Heritage - 10/14/1970 - C.S. File 54/119-3

Reported as not found.

Corner destroyed by R/W logging & high water.