

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5324)

-----  
Set yew post, 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 3, 4, 9, & 10, marked T27S S 3 on NE, R8W S 10 on SE, S 9 on SW, S 4 on NW faces, with 5 notches on S & 3 notches on E edges; from which  
A fir, 4" dia., bears N.76°E., 77 lks. mkd: T27S R8W S3 BT  
A fir, 48" dia. bears S.27°E. 72 lks. mkd: T27S R8W S10 BT  
A fir, 18" dia. bears S.60°W., 82 lks. mkd: T27S R8W S9 BT  
A fir, 48" dia. bears N.58°W. 109 lks. mkd: T27S R8W S4 BT

Douglas Co. Surveyors Office - John M. Powell - 10/21/1970 - C.S. File 54/119-5

-----  
Reported as not found.  
Had good line from ridge top north approx. 14 chs to approx sec. cor. some old burnt snags in area. Fd. old blaze on one snag.

BLM dependent resurvey by Harvey E. Wofford & John P. Farnsworth, Cadastral Surveyors under Group # 981 & 1065, surveyed May 1979/July 1981 - (DCSO records Vol. 44 Page(s) 17044)

-----  
Point for the cor. of secs. 3, 4, 9, & 10 proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 26" in the ground, with brass cap marked:  
T 27 S R 8 W  
S 4 | S 3  
S 9 | S 10  
1979

from which  
A fir, 22" dia. bears N.47°E., 38 lks. mkd: T27S R8W S3 BT  
A fir, 18" dia. bears S.71°E. 53 lks. mkd: T27S R8W S10 BT  
A fir, 18" dia. bears S.6°W., 33 lks. mkd: T27S R8W S9 BT.  
A fir, 20" dia. bears N.51°W., 25 lks. mkd: T27S R8W S4 BT