

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34, T26-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by - A. R. and S.C.Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 11 Page(s) 4642)

Set post, (on East bank of stream) 4 ft. long, 4" sq., for cor. to secs. 3, 4, 33 and 34, from which
A Cedar 12" , bears N.70°E., 10 lks. dist.
A Hemlock 6", bears N.55°W., 11 lks. dist.
A Hemlock 8", bears S.50°E., 25 lks. dist.
A Cedar 6", bears S.40°W., 62 lks. dist.

Shaner Engineering - For: Hub Lumber Company - June 24, 1974
RM 2-63

Set PK nail on the face of a 15 ft. high rock cliff, from which a Brass Cap, I mkd. Witness Corner, South 3 ft. to T26S R8W S33 S34; T27S R8W S4 S3 1974, bears North 3.0 ft.
14" Cedar, I scribed "T26S R8W S34 BT", bears N.13°E., 17.9 ft.
30" D.Fir, I scribed "T26S R8W S33 BT", bears N.50°W., 108.0 ft.
18" D.Fir, I scribed "T27S R8W BT", bears S.8°E., 26.0 ft.
16" D.Fir, I scribed "T27S R8W S4 BT", bears S.18°W., 33.2 ft.
No original evidence found. Panther Creek lies 20 ft. North. Area has been badly burned and corner area may have been badly eroded by Panther Creek.

Cor. Fd. and Used in BLM resurvey by Wofford & Farnsworth, Cadastral Surveyors, under Group #'s 981 & 1065, surveyed 1979/1981 - (DCSO records Vol. 44 Page(s) 17042)