

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5325)

Set fir post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N face; from which

A fir, 40" dia., bears N.70°W., 74 lks., mkd: ¼ S BT.

A fir, 20" dia., bears S.45°W., 30 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - 10/21/1970 - C.S. File 54/119

Reported as not found.

This cor. falls on ridge that is very badly burnt some large snags in area but no evidence of faces - Paced out call on top of ridge for 11 chains with no results.