

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 548100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 2 only, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5783

Set ¼ sec. post, from which
A Fir 15" dia., bears N.8°E., 12 lks.
A Fir 12" dia., bears S.14°W., 13 lks.

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5278)

No trace of ¼ sec. cor. on N. side of sec. 2.

Douglas Co. Surveyors Office - John M. Powell, and crew - April 24, 1970 - C.S. File 54/113-8

Looked for, not found.
Corner lies at top of high bluffs. All timber to the south has been cut and burnt. No trace of original evidence.

Gary Smithers - For: Roseburg Resources Co. - June 2007 - M153-42

Set - 5/8"x30" iron rod w/2½" alum cap mkd per 1973BLM manual
6" D.Fir N.10°W., 9.2 ft. to spike side center scribe
"T28 R8W ¼ S2 BT" with alum tag.
10" D.Fir N.18°E., 16.7 ft. to spike side center scribe
"T28 R8W ¼ S2 BT" with alum tag.
11" D.Fir S.8°E., 9.9 ft. to spike side center scribe
"T28 R8W ¼ S2 BT" with alum tag.
23" D.Fir S.28°E., 22.2 ft. to spike side center scribe
"T28 R8W ¼ S2 BT" with alum tag.

Ron Rice, NW Land Surveying - June 2013 - C.S. File 65/78-48

Condition report only
Found - 2½" alum. cap, dated 2007, with the following accessories:
8" D.Fir bears N.10°W., 9.2 ft. - healed face
12" D.Fir bears N.18°E., 16.7 ft. - healed face
12" D.Fir bears S.8°E., 9.9 ft. - healed face
26" D.Fir bears S.28°E., 22.2 ft. - scribing visible
Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East