

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 442700

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 34 only; T27-1E

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO Survey by Samuel C. Flint, Deputy Surveyor, under Contract No. 473, dated June 5, 1883 - (DCSO Records Vol. 23 Page(s) 9829 & Vol. 24 Page(s) 10244)

Set post 44x4" firmly in the ground for stan. ¼ sec. cor. mkd S C on N and S faces, from which

 A fir, 18" dia., bears S.40°E., 21 lks., mkd: S C ¼ S BT.

 A fir, 16" dia., bears N.2°W., 27 lks., mkd: S C ¼ S BT.

GLO resurvey by Lincoln E. Wilkes, US Cadastral Engineer, Otto L. Draper & Norman D. Price, US Transitmen, under Special Instr. dated Dec. 21, 1920 - (DCSO records Vol. 24 Page(s) 10266-7)

The old established for standard ¼ cor. of Sec. 34 bears S.19¾°W., 63 lks. (and East 7.01 chs.)

I destroy all evidence of this cor.

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for standard ¼ sec. cor., with brass cap marked

SC
¼ S 34

1927

from which

 A fir, 14" dia., bears N.75°E., 21 lks., mkd: ¼ S34 SC BT.

 A fir, 30" dia., bears N.55°W., 57 lks., mkd: ¼ S34 SC BT.

(1/4 Cor. Sec. 3 bears West 1.61 chs.)

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18932)

The standard ¼ sec. cor. of sec. 34 only, T27S R1E WM monumented with a 1" dia., iron post, 10" above the ground, firmly set, with a 2½" dia. GLO brass cap properly marked, from which the original BTs are at record measurements and in good condition.