

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 801010

PRIMARY CORNER DESCRIPTION Cor. No 1 Roy #1 Mill Site; MS 1008B

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18923-4)

Set a 2½" dia. aluminum pipe, 30" long, 20" in the ground, with a 3" dia. alum. cap mkd. R1-1-MS1008B 1992, from which The cor. of secs. 2, 3, 10 and 11, T28S R1E WM, bears N.88°19'14"W., 311.29 ft.;

A fir, 9" dia., bears S.20°05'W., 46.20 ft., mkd. R1-1-1008B BT.

A hemlock, 18" dia., bears S.76°30'W., 21.52 ft., mkd. R1-1-1008B BT.