

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 801020

PRIMARY CORNER DESCRIPTION Cor. No. 3 Roy #1 Mill Site; MS 1008B

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18925)

This corner falls at the westerly edge of road turnout. Set a 5/8" dia. iron rod, 30" long, 6" below ground surface, with a 1½" dia. aluminum cap mkd. R1-3-MS1008B 1992, from which

- A fir, 8" dia., bears S.87°30'E., 84.70 ft., mkd. R1-3-1008B BT.
- A fir, 8" dia., bears S.47°10'E., 149.76 ft., mkd. R1-3-1008B BT.