

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 803020

PRIMARY CORNER DESCRIPTION Cor. No. 3 Roy #2 Mill Site; MS 1008B

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18925)

This corner falls in a gravel road. Set a 5/8" dia. iron rod, 30" long, 4" below road surface, with a 1½" dia. aluminum cap mkd. R2-3-MS1008B 1992, from which

A fir, 10" dia., bears N.28°05'E., 55.41 ft., mkd. R2-3-1008B BT.

A fir, 10" dia., bears S.60°00'E., 49.02 ft., mkd. R2-3-1008B BT.