

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 803030

PRIMARY CORNER DESCRIPTION Cor. No. 2 Roy #2 Mill Site; MS 1008B

Alias _____	Description <u>Cor. No. 4 Roy #3 Mill Site</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18925)

Corner No. 2, identical with Cor. No. 4 of the Roy No. 3 mill site, of this survey.

Set a 2½" dia. aluminum pipe, 30" long, 25" in the ground, with a 3" dia. aluminum cap mkd. R2-2 R3-4-MS1008B 1992, from which

A fir, 9" dia., bears S.52°55'E., 23.30 ft., mkd. R2-2-1008B BT.

A fir, 8" dia., bears S.56°05'W., 22.72 ft., mkd. R3-4-1008B BT.