

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 804010

PRIMARY CORNER DESCRIPTION Cor. No. 3 Roy #3 Mill Site; MS 1008B

Alias _____	Description _____	Cor. No. 3 Roy #4 Mill Site
Alias _____	Description _____	Cor. No. 4 Roy #6 Mill Site
Alias _____	Description _____	
Alias _____	Description _____	

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18926)

Corner No. 3, identical with Cor. No. 3 of the Roy No. 4 mill site, and Cor. No. 4 of the Roy No. 6 mill site, all of this survey.

Set a 2½" dia. aluminum pipe, 30" long, 25" in the ground, with a 3" dia. aluminum cap, mkd. R3-3 R4-3 R6-4-MS1008B 1992, from which

- A fir, 18" dia., bears N.63°00'E., 4.50 ft., mkd. R3-3-1008B BT.
- A fir, 13" dia., bears N.72°10'W., 19.33 ft., mkd. R6-4-1008B BT.