

TOWNSHIP 28 RANGE 01E POINT IDENTIFIER # 805010

PRIMARY CORNER DESCRIPTION Cor. No. 4 Roy #4 Mill Site; MS 1008B

Alias _____	Description <u>Cor. No. 4 Roy #5 Mill Site</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18927)

-----

Corner No. 4, identical with Cor. No. 4 of the Roy No. 5 mill site, of this survey.

This corner falls in clearcut area. Set a 2½" dia. aluminum pipe, 30" long, 24" in the ground, in a mound of stone, 3 ft. base, to top, with a 3" dia. aluminum cap mkd. R4-4 R5-4 R6 MS1008B 1992, from which

No local bearing objects or bearing trees available.