

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 100474

PRIMARY CORNER DESCRIPTION Sec Cor for 12 & 13 only, T28-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882  
- (DCSO records Vol. 13 Page(s) 5424-25)

-----  
Set Cedar post 4 ft. long, 4" long, 4" sq., 24" in the ground  
for cor. to secs. 7, 12, 13 and 18 and marked T28S S7 on NE.;  
R2W S18 on SE.; R3W S13 on SW.; and S12 on NW. faces, with 2  
notches on N. and 4 on S. edges, from which

A Fir 8" dia., bears N.50°E., 3 lks. dist. mkd. T28S R2W  
S7 BT.

A Cedar 12" dia., bears S.20°E., 19 lks. dist. mkd. T28S  
R2W S18 BT.

A Maple 8" dia., bears S.15°W., 2 lks. dist. mkd. T28S R3W  
S13 BT.

A Cedar 10" dia., bears N.50°W., 9 lks. dist. mkd. T28S  
R3W S12 BT.

The corner is about 1000 ft. above the creek, near the summit  
of mountain.

GLO survey by William N. Gibb, Deputy Surveyor, under  
Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13  
Page(s) 5475)

-----  
(After established cor. for 7 & 18) "I destroy markings on  
other corner and bearing trees referring to secs. 7 and 18."

Douglas Co. Surveyors Office - James Byron, Deputy - John  
Powell & Wm. Stoffel, crew - Sept. 1962 - C.S. File 52/126-49

-----  
Found - Orig. 10" now 30" Cedar N.50°W., 6.0 ft., shows  
scar. I do not open.

Orig. 8" now 14" Fir N.50°E., 2.0 ft., opened to old  
face, scribing destroyed, see record of 1910  
survey.

Orig. 10" now 30" Cedar, shows scar.

Did not find SE. BT.

Set brass cap at cor. mkd. County Surveyors Office 1962

T 28S

S 12

R3W S 13 | R2W

New BT - 8" R.Fir bears S.37°W., 34.4 ft scribed S13 T28S R3W  
CS BT.

Fd. OK, March 1980 by BHW Engineering - M 83-19