TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5476)

Set granite stone 10x12x20", 15" in the ground for cor. of secs. 5, 6, 7, & 8 mkd with 5 notches on E & 4 notches on S edge, from which

An oak, 8" dia., bears N.60°E., 89 lks., mkd: T28S R2W S5 BT.

A laurel, 8" dia., bears S.70°E., 86 lks., mkd: T28S R2W S8 BT.

A laurel, 10" dia., bears S.20°W., 66 lks., mkd: T28S R2W S7 BT.

A laurel, 7" dia., bears N.40°W., 70 lks., mkd: T28S R2W S6 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - April 24, 1968 - C.S. File 54/26-9

Found - Orig. 8", now 16" Live Oak, N.65°E. 58.7 ft. (slope) (Rec. N.60°E.) Alive, shows good scar.

Orig. 8",now 15" Laurel, alive, S.60°E. 56.8 ft., burnt out, no scribe found, rec. bearing S.70°E.

Orig. l0", now 17" Laurel, alive, S.20°W. 43.6 ft., Open & find scribe and reverse. .

Orig. 7",now 15" Laurel, N.45°W. (Rec.N.40°W.) 46.2 ft., alive, opened by D. Wright, U.S. Plywood, scribe visible in poor cond.

At cor., point, the intersection of 3 distances & one good bearing to SW:

Set - Brass Cap at Cor. mkd:. County Surveyors Office 1968

T28S R2W

S 6	S 5
S 7	S 8

New BTs- 6" Live Oak S.33°E. 10.8 ft. Mkd. T28S R2W S8 CS BT.

7" Live Oak N.67°W. 45.8 ft. mkd. T28S R2W S6 CS BT.

16" Live Oak N.66°E. 58.7 ft. (slope) Mkd. T28S R2W S5 CS BT. (Orig. BT)

18" Laurel S.32°W. 35.0 ft. Mkd. T28S R2W S7 CS BT.

Note - This corner lies on steep SW slope.