TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5453)

Set cedar post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S28 on N & 33 on S face; from which
A cedar, 24" dia., bears S.13°E., 53 lks., mkd: ¼ S33 BT.
A hemlock, 10" dia., bears N.55°E., 9 lks., mkd: ¼ S28 BT.

Douglas Co. Surveyors Office - John Powell - W. Penley - J. Heritage - V. Perron - July 1971 - C.S. File 54/26-1

Found - 24" cedar now 32" S.13°E., 35.0 ft. Shows very good scar.
10" hemlock now 16" N.55°E., 5.9 ft. shows very good scar.

Note - As trees hit bearing & dist. also hit call of one chain east of creek, I do not open.

Set - Brass cap at ¼ cor. mkd: COUNTY SURVEYORS OFFICE 1971 T28S R2W ¼ S 28 / S 33

All trees in good shape & tagged.