

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5433)

Set granite stone 12x12x18 ins., 12" in the ground for ¼ sec. cor., marked ¼ on N. face, and raise mound of stone 2 ft. base, 1½ ft. high N. of cor., from which
A Fir 7" dia., bears N.36°E., 32 lks. dist., mkd. ¼ S34 BT.
No other tree fit to mark.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6239)

The ¼ sec. cor., which is a granite stone, firmly set, marked and witnessed as described by the surveyor general, except that no trace of the mound of stone could be found. I re-witness this cor., as follows: from cor.
A Fir 24" dia., bears N.81°30'W., 81 lks. dist., mkd. ¼ S34 BT. (New BT)
A Fir 7" dia., bears N.36°E., 32 lks. dist., mkd. ¼ S34 BT. (Old BT)

Douglas Co. Surveyors Office - Dennis Gaylord, U.S.F.S. (Deputized by County), Wit: Randal Lopez - April 6, 1978 - C.S. File 59/46-49

Found - Orig. corner stone 12"x12"x18" marked "¼". Stone is loose and lying at top of road cut, directly up-slope from where I have determined the true corner point to be.
A 30" Fir stump bears N.36°30'W., 53.46 ft. (Rec. N.81°30'W., 53.46 ft.) scribing visible on partly healed blaze which does face corner "¼ S34 BT"
Stump hole bears N.35°E., 21.12 ft. (Rec. N.36°E., 21.12 ft.)
Corner for secs. 3 and 2 only, T29-2, bears East 258.01 ft. (Rec. S.89°58'E., 253.44 ft.)
Corner falls in ditch line of road, so I SET a 5/8" x 24" Iron rod at corner point. (F.S. Road #274)
New Accessories:
11" D.Fir bears N.45°30'E., 14.0 ft. scribed "¼ S34 CS BT" on a double blaze.
12" D.Fir bears N.9°W., 12.5 ft. scribed "¼ S34 CS BT" on a double blaze.
(Cont. Next Page)

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

I bury the original corner stone between the new BTs. 4" of the stone is above ground and the "¼" is facing North. The stone bears N.19°E., 12.1 ft.

A 2½" brass cap on a 1" I.P. bears East 70.0 ft. from corner point, stamped: County Surveyors Office T 28 S R 2 W
¼ S 34
W.C.
← West
70.0'
1978

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 10/5/2018 (filed 11/10/2021) - C.S. File 67/49-23

The 1978 brass cap was searched for and not found. The original corner position is being restored from C.S. 59/46-49 Witness Corner and the Section Corner of 2&3 T28S R2W. I set the new corner monument 70.0 ft. due West of the Witness Monument, The aforementioned Section Corner of 2&3 bears, S.89°58'E., 258.57 ft. from the new monument. Set - A 5/8"x17" iron rod 2" below ground in solid rock with a yellow DCS0 yellow plastic cap marked
DOUGLAS CO
SURVEYOR

BT by Gaylord in 1978 -
A 20" dia. D.Fir bears, N.45°30'E., 15.5 ft. with fully healed blaze (rec 14.0 ft matches face measurement)
A 21" dia. D.Fir bears, N.9°W., 13.5 ft. with fully healed blaze (rec 12.5 matches face measurement)
A 12"x12" granite corner stone projecting 4" bears N.19°E., 12.1 ft. (Original 1908 stone by Gibb was reset by Gaylord 1978)

Note- All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.
The corner falls in the ditch of National Forest Road 2810 on the North side.
Compass declination - 15°E.