

PRIMARY CORNER DESCRIPTION CC Secs. 14 & 23, West

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5437)

-----  
Set fir post, 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 14, 15, 22, & 23, marked T28S S 14 on NE, R2W S 23 on SE, S 22 on SW, S 15 on NW faces, with 2 notches on S & E edges and dig pits, 18x18x12" in each sec., 5½ ft. dist. & raise mound of earth, 3½ ft. base, 1½ ft. high, W of cor.; from which

- A fir, 10" dia. bears N.20°E., 29 lks mkd: T28S R2W S14 BT
  - A fir, 14" dia. bears S.69°E., 29 lks mkd: T28S R2W S22 BT
  - A fir, 7" dia. bears N.39°W., 16 lks. mkd: T28S R2W S15 BT
- No other tree fit to mark.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 13 Page(s) 5497-8)

-----  
The cor, established for secs. 14, 15, 22 & 23 which is a fir post, 12x4x4" above ground, firmly set, marked T28S S15 on NW; R2W S 22 on SW; face, with 3 notches on S and 2 notches on E edge. **Hereafter, this cor. will refer to secs. 15 and 22 only.** No marks are found on NE and SE faces; from the corner

- A fir, 20" dia., bears S.69°W., 29 lks., mkd: T28S R2W S22 BT; old BT
- A fir, 10" dia., bears N.39°W., 16 lks., mkd: T28S R2W S15 BT; old BT.

The orig. BT, in sec. 14, not found.

**N.0°14'E., 0.89 chs.**

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 14 & 23, with brass cap marked

	T28S
S15	S 14
	S 23
	R2W
	1923

from which

- A fir, 13" dia. bears N.32°E., 36 lks mkd: T28S R2W S14 BT
- A hemlock, 8" dia., bears S.71°E., 18 lks., mkd: T28S R2W S23 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - 7/6/1973 - C.S. File 56/34

-----  
Sec. cor. of S15 | S14 which is a 1923 GLO brass cap and BTs  
                  | S23 in good cond.