

PRIMARY CORNER DESCRIPTION CC Secs. 2 & 11, West

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5439)

-----  
Set fir post, 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 2, 3, 10, & 11, marked T28S S 2 on NE, R2W S 11 on SE, S 10 on SW, S 3 on NW faces, with 5 notches on S & 2 notches on E edges and dig pits, 18x18x12" in each sec. 5½ ft. dist and raise mound of earth, 3½ ft. base 1½ ft. high W of cor., from which

- A fir, 14" dia. bears N.50°E., 24 lks. mkd: T28S R2W S2 BT
  - A fir, 12" dia. bears S.40°W., 46 lks mkd: T28S R2W S10 BT
  - A fir, 12" dia. bears N.58°W., 36 lks. mkd: T28S R2W S3 BT
- No other tree fit to mark.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 13 Page(s) 5501-2)

-----  
The cor. established for secs. 2, 3, 10 and 11, which is a fir post, 12x4x4" above ground, firmly set, in good condition, marked T28S S3 on NW and R2W S10 on SW face. No marks are found referring to secs. 2 and 11, and **hereafter this corner will refer to secs. 3 & 10 only;** from the corner

- A fir, 12" dia., bears S.40°W., 46 lks., mkd T28S R2W S10 BT; old bearing tree.
- A fir, 12" dia., bears N.58°W., 36 lks., mkd T28S R2W S33 BT; old bearing tree.

The original bearing tree, in sec. 2, is missing.  
N.0°3'E., 0.60 chs.

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 2 & 11, with brass cap marked

	T28S
	S 2
¼	S11
	R2W
	1923

from which

- A fir, 6" dia., bears N.77°E., 25 lks. mkd: T28S R2W S2 BT
- A cedar, 10" dia., bears S.72°E., 30 lks., mkd: T28S R2W S11 BT.