

TOWNSHIP 28 RANGE 03E POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Herbert N Raymond, U.S. Cadastral Engineer, under special instructions dated Dec. 27, 1920, Surveyed Aug 1928/Aug 1929 - (DCSO records Vol. 25 Page(s) 10523-4)

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, to bed rock, and raise a mound of stone, 2 ft. base, 1 ft. high, around the post, for ¼ sec. cor., with brass cap marked

¼
S 9|S 10
1929

from which

A larch, 16" dia., bears S.60°E., 34 lks., mkd: ¼ S10 BT.

A fir, 12" dia., bears N.12°W., 58 lks., mkd: ¼ S9 BT.

Burton W. Holt - With: A. Keatley - Aug. 19, 1969 - C.S. File 55/133

I removed Brass Cap for Road Construction and referenced the spot for later replacement (1966)
Old Fir Bearing Trees destroyed in construction.
Reset the Brass Cap and set two new Bearing Trees in Aug. 1969.

A 14" Shasta bears N.18°W. 52.5 ft mkd: "¼ S9 BT". (Shasta Fir)

A 28" Shasta bears S.87°E. 87.5 ft. Mkd: "¼ S10 BT. (Shasta Fir)

This corner is in the road fill approximately 15 ft. from road shoulder.