

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 16 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by - S.C. Flint, Under Contract #459, dated Aug. 3, 1882 (DCSO records Vol. 13 Page(s) 5531)

Set cedar post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N & S faces; from which

A fir, 36" dia., bears N.55°W., 14 lks., mkd: ¼ S BT.

A fir, 18" dia., bears S.20°W., 14 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - John Powell - Wm. Stoffel - July 1962 - C.S. File 52/126-17

Search for ¼ cor. 16/21

Found - Now 30" fir faces to west previously opened, shows good scribing "¼ S2" this BT scribed about 50 years ago (ring count)

We also find now 15" cedar that shows good scribing "¼ S 16 BT" This tree scribed about 20 years ago, faces S.20°W.

30" fir bears S.29°E., 57.0' from cedar BT.

We ran a compass line from section cor. 15, 16, 21, & 22 to this ¼ cor. & notice at least two other blazed sect. lines.

Swamp boundary line is irregular but it appears call is ok.

I believe 1910 surveyor scribed Fir BT but is not of record.

David Edwards - For: Seneca Jones Timber Co. - 10/2000 - C.S. File 65/29-10

Found - A diligent search was made, with negative results. Near the south ¼ corner a cedar & fir (now a stump) called for in the County Surveyor's 1962 search notes. Inquiries to survey staff at the Umpqua National Forest Office & local & state BLM offices produced no information as to the origin of the scribed trees, I therefore set the south ¼ corner at the proportionate distance between the sec. corners.

Set - 5/8"x36" steel pin W/ 2½" dia., alum. cap mkd: "T28S R3W ¼ S16 LS 2339 2000"

The previously scribed Cedar (now 22" dia., & rescribed "¼ S16 BT" to face the new corner) bears N.56°W., 25.75 ft.

A 17" dia., Cedar bears N.1°E., 9.95 ft. ("¼ S16 BT) BTs are measured to center of tree at root crown.

FD. ok by D.Edwards, 3/2008 C.S. file 65-64-3