TOWNSHIP 28 RANGE 03 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION N 1/4 Cor. Sec. 16 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5584)

Set stone, 6x8x14", 10" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which
A fir, 48" dia., bears S.14°E., 38 lks., mkd: ¼ S16 BT.
A hemlock, 24" dia., bears N.17°E., 56 lks., mkd: ¼ S9 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S. Bilow - Oct. 1957 - C.S. File 49/22-3

Found - Both orig. BTs & broken stone at corner marked ¼ on East face.
Orig. 48" now 48" R.Fir S.48°E., 25.1 ft. shows scribed on loose bark "¼ S BT"

Set brass cap at corner mkd ¼ S 9 / S 16 T28S R3W County Surveyors Office 1957

New BTs- 10" yewood bears S.48°E. 76.5 ft scribed ¼ S16 CS BT
14" cedar bears N.70½°E., 11.5 ft scribed ¼ S9 CS BT

Note - It was determined when the GIS layer was computed that this is not a common corner. DCSO 3/26/2009