

TOWNSHIP 28 RANGE 03 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5566)

Set granite stone 6x8x12", 8" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which
 An alder, 16" dia., bears N.48°E., 22 lks., mkd: ¼ S22 BT.
 A cedar, 18" dia., bears S.37°E., 8 lks., mkd: ¼ S27 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - John Powell - Wm Stoffel - Sept. 1962 - C.S. File 52/126-56

Found - Orig. 18", now 22" Cedar Snag, shows good scribing, "¼ S27 BT".
 Orig. 16" Cedar, not Alder, N.23°W. 15.4 ft., not N.48°E. 14.5 ft., shows good scribing "¼ S22 BT".
 Also find corner stone in place.
Set - Brass cap alongside corner stone & mkd:
 County Surveyors ¼ S 22 T28S
 Office, 1962 ¼ S 27 R3W
New BT - 9" R.Fir bears S.8°E., 44.2 ft. scribed ¼ S27 CS BT.