

TOWNSHIP 28 RANGE 03 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by - S.C. Flint, Under Contract #459, dated Aug. 3, 1882 (DCSO records Vol. 13 Page(s) 5545)

Set cedar post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N & S faces; from which

A cedar, 6" dia., bears N.22°W., 9 lks., mkd: ¼ S BT.

A fir, 36" dia., bears S.5°E., 25 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - John Powell - Wm. Stoffel - Aug. 1962 - C.S. File 52/126-36

Found - Orig. 6" now dead, 10" cedar N.22°W., 5.9 ft. shows good scribing "¼".

Orig. SE BT down & out of place.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS ¼ S 10 T28S R3W
OFFICE 1962 S 15

New BTs- 18" Cedar bears N.27°W., 19.2 ft scribed ¼ S10 CS BT

6" yewood bears N.31°E., 55.0 ft scribed ¼ S10 CS BT

No trees near to south.

Corner is at West edge of old logging road.