

TOWNSHIP 28 RANGE 03 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5558)

Set granite stone 6x8x15", 10" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
 A cedar, 14" dia., bears N.62°W., 7 lks., mkd: ¼ S27 BT.
 A fir, 6" dia., bears N.54°E., 35 lks., mkd: ¼ S26 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - John Powell - Bill Stoffel - Aug. 8-10, 1962 - C.S. File 52/126-26

Found - Stone, broken, at corner & both BTs as recorded.
Set - Brass Cap alongside Cop. Stone & Mkd County Surveyors S27|S26 T28S R3W Office, 1962
 Orig. 6" Fir N.54°E. 23.8 ft. now dead, shows scribing.
 Orig. 14" Cedar, now 24", N.62°W. 4.6 ft., shows scar.
New BT - 10" W. Fir bears S.82°E. 23.4 ft. scribed ¼ S26 CS BT

Noted on the visual page:
BRASS CAP REMOVED 1966
We have no record of who made this notation or why the cap was removed. DCSO JC 2/26/2009

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 3/2/2009 - C.S. File 67/28-22

Area logged and burnt in mid 60's?
No evidence of corner found.
A surveyed position would be helpful in refining a search area, and may yield evidence of the corner.