

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 14 only, South

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by - S.C. Flint, Under Contract #459, dated Aug. 3, 1882 (DCSO records Vol. 13 Page(s) 5533)

Set cedar post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked on N & S faces ¼ S. from which
 A cedar, 12" dia., bears N.40°E., 40 lks., mkd: ¼ S BT.
 A hemlock, 24" dia., bears S.60°W., 19 lks., mkd: ¼ S BT.

Thomas E. Shrum, Jr. - For: US Plywood Corp. - Dec. 1960 - M11-79

Found - 24" hemlock S.60°W., 12.5 ft. (down & rotten)
 12" cedar N.40°W., 26.4 ft.
 Set - ¾"x36" iron rod
 12" hemlock N.87°E., 29.0 ft.
 10" yew N.60°30'W., 18.0 ft.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2274, Surveyed Oct/Nov 2009 - (DCSO records Vol. 56 Page(s) 22294)

The ¼ sec. cor. of sec. 14 only, perpetuated by Shrum, Jr., in 1960, monumented with a rebar, 36". long, 3/4" dia., firmly set, projecting 8" above ground, bent E., from which the remains of the orig. bearing trees
 A burnt, decayed, sawed cedar stump, size indeterminate, bears N.40°E., 25.9 ft., with no marks visible.
 A roothole bears S.60°W., 12.5 ft.
 and the remains of bearing trees mkd. by Shrum, Jr.
 A splintered, decayed hemlock stump, size indeterminate, bears N.88½°W., 28.1 ft., with no marks visible.
 A sawed yew stump, 10" dia., bears N.63°W., 18.5 ft., with no marks visible.

At the corner point
 Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, with brass cap mkd.

T28S R3W
 ¼ S 14
 2009

from which new bearing trees
 A fir, 13" dia., bears N.68°E., 8.2 ft., mkd. X BT.
 A fir, 14" dia., bears N.14¼°W., 11.2 ft., mkd. ¼ S14 BT.
 Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.
 Place the rebar inside and deposit a magnet in a white plastic case at the base of the stainless steel post.
 N¼ corner Sec. 23 only bears N.89°52'48"E., 96.57'