

TOWNSHIP 28 RANGE 03 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 24; & 19, T28-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5429)

-----  
Set lava stone 7x10x14 ins., 10" in the ground for ¼ sec. cor. marked ¼ on W. face, from which  
A Yew 7" dia., bears S.13°E., 23 lks. dist. mkd. ¼ S19 BT  
A Hemlock 16" dia., bears S.58°W., 37 lks. dist. mkd. ¼ S24 BT.

Survey by Victor McLind - For: Umpqua National Forest - Sept. 1978 - M 70-36

-----  
Set concrete monument approx. 6" wide on top 12" wide at bottom, 18" high, on steep NW. rock slope. 3" brass disk in top of concrete mon. stamped "T28S R3W S24 S19 R2W RLS 934 1978", from which  
10" Yew, O.B.T., bears S.13°E., 15.2 ft. (23 lks.), good face with scribing visible. Tree is down but alive.  
16" Hemlock, O.B.T., bears N.58°W.,, 24.4 ft. (37 lks.), No remains of face found. Tree is down and almost completely rotted away. Rotted stump hole apparent.  
10" Hemlock bears N.6°30'W., 26.9 ft. I blazed and scribed "T28S R3W ¼ S24 BT". New BT.  
12" Hemlock bears N.83°E., 5.8 ft. I blazed & scribed "T28S R2W ¼ S19 BT". New BT.