

PRIMARY CORNER DESCRIPTION Center North 1/16 Sec. 6

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

C.C. Boyer, Deputy Co. Surveyor, June, 1913 For: L. Hatfield
Volume 2 Page 176 - F.B. 35 Pages 3-11

Set post 4x4x36 mkd: CS 1/16 S, from which:
A Red Fir. 18" dia., marked CS 1/16 S BT bears N.51°E., 5
lks.
A Red Fir. 18" dia., marked CS 1/16 S BT bears N.49½°W.,
41 lks.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 11/17/1999 - C.S. File 66/13-12

Located survey corner per Vol. 2 Pg. 176, 1913

Found - 18" now 19" dia., 2½ ft. high rotted D.Fir stump,
scribing fd: "1/16" bears N.51°E., 3.3 ft. 1913
18" now tipped out of ground rotted D.Fir stump.
Scribing fd: "CS 1/16S BT" Root wad bears
N.49½°W., 27.1 ft. 1913
Set - 5/8"x30" long iron rod with DCSO plastic cap flush
with ground.
18" dia., broken top D.Fir single blazed & scribed
"X BT" bears S.8°E., 7.9 ft.
20" dia., D.Fir single blazed & scribed "X BT" bears
N.23°W., 9.7 ft.
Fence corner with fence line running south & west is
approx. N.74°W., 115 ft.
Note - Set I.R. and BTs to perpetuate old survey point from
1913 Vol. 2 Pg. 176 CN 1/16 Sec. 6 BTs scribed
low on trunk.