

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5642)

Set Laurel Post for the cor. to secs. 5, 6, 7 and 8, from which

- An Oak 20" dia., bears N.60°E., 42 lks. dist.
- A Laurel 20" dia., bears S.20°E., 36 lks. dist.
- A Laurel 15" dia., bears S.40°W., 40 lks. dist.
- A Laurel 20" dia., bears N.10°W., 35 lks. dist.

John Markham - For: Geo. Vaughn; Harry Collison - April 8, 1951 - C.S. File 40/277)

Determined by an O.B.T., A Laurel 20" dia., bears S.20°E., 23.0 ft. scribed S 7, T 28 S R 4 W, "O.B.T."

At corner point, set Wood post, from which

- A Fir 11" dia., bears S.49°E., 26.0 ft. mkd. S8 BT.
- A Laurel 14" dia., bears S.74°W., 38.0 ft. mkd. S7 BT.
- A Laurel 14" dia., bears N.27°W., 47.0 ft. mkd. S6 R4W BT.
- A Laurel 38" dia., bears N.30°E., 17.0 ft. mkd. S5 T28S R4W 2880, B.T.

The scribe on the OBT was very plain and faced N.20°W., however since this tree was scribed S7, it belonged in the SW¼, no other trees would fit the field notes but I feel that the 38" La., I scribed was on OBT the gov't notes being in error. (Added 8/14/2024 JC DCSO)

Doug. County Surveyors Office - James Byron, Deputy - S.A. Bilow - April 20, 1959 - C.S. File 49/67-4

Found - All four BTs as scribed by Markham, 1951.
Also find Orig. 15" now 20" Laurel, previously opened, shows good scribing "S7 T28S R4W".
Markham used this BT for the orig. SE BT. I believe it is the orig. SW BT. Not only is it mkd. for the SW BT, but faces to NE.
Find no other orig. BTs except I do find now 40" Laurel bears N.40°W., (Rec. SW), 23.1 ft. rec. 20" Laurel N.10°W., 23.1 ft., center rotted, no scribing found.
Find 60" R.Fir bark blazed & scribed "S S / 9 0" bears S.80°E., 36.0 ft., real old scribing, no record of this BT.

I destroy all scribing by Markham and set brass cap at true corner mkd: County Surveyor's $\begin{array}{c|c} S 6 & S 5 \\ \hline S 7 & S 8 \end{array}$ T28S R4W
Office, 1959

Markham's corner, N.84°W., 25 ft.
(Cont. Next Page)

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. 5, 6, 7 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs -20" R.Fir bears S.3°E., 14.0 ft. scribed S8 T28S R4W
CS BT.
12" R.Fir bears S.17°W., 15.8 ft. scribed S7 T28S
R4W CS BT.
56" R.Fir bears N.69°E., 51.8 ft. scribed S5 T28S
R4W CS BT.
10" R.Fir bears N.6°W., 22.3 ft. scribed S6 T28S R4W
CS BT.

Found OK, BLM resurvey by Lynn Roseberry, under Group #636 -
Survey, May/June 1967 (DCSO records, Vol. 34 Page 14197)

and Fd. OK, BLM survey by Popkens, Group #837, Survey, 1974
(DCSO records, Vol. 37 Page 15372)

and Fd. OK, BLM survey by Rogers & Bishop, 1984, (DCSO
records, Vol. 47 Pages 17986-87)

Fd. OK, Glenn Baughman, July 1991, M 113-49

David Edwards - For: Seneca Jones Timber Co. - Nov. 2014 -
M168-67

Found - Brass cap
30" Fir bears S.7°E., 14.2 ft.
15" fir bears S.16°W., 15.8 ft.
16" fir bears N.8°W., 22.4 ft.
All with healed blazes.
Set - 6 ft. steel post S.84°35'44"E., 2 ft.