

PRIMARY CORNER DESCRIPTION Center ¼ for section 29.

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Doug. County Surveyors Office - G.G. Stewart, Deputy. Nov. 1, 1922. Vol. 3, Pg. 127 & C.S. File no. 5/27.

-----  
Compute center position, setting it midway between ¼ corners on north & south sides, and east & west sides.  
Set - Drove Iron Pipe for corner and marked:  
New BTs - 18" Fir, N.88½°W., 90.4'.  
          24" Fir, S.57½°E., 52.6'.

Howard W. Johnstone, for: Roseburg Resources Co. Feb. 1986 M 100-36.

-----  
WITNESS CORNER - CORNER FALLS ON BRIDGE.  
Set - 5/8"x36" Iron rod and aluminum cap mkd: 'LS498' witness corner lies 22.0' south of true corner position.  
New Bts - 11" Cedar, bears N.61°W., 20.8' - scribed.  
          26" Fir, bears S.5°E., 31.5' - scribed.  
Note - Tagged fence corner bears S.25°14'W. 53.0'.  
Found no evidence of 1922 corner information.

Fd. Ok by K.DeGroot, May 1997 - M124-53

BLM resurvey by George M. Winter & A Bert Skeesick, Cadastral Surveyors, under Group No. 2729, surveyed Nov. 2013/Oct. 2014 - (DCSO records Vol. 58 page(s) 23240)

-----  
Point for the center ¼ sec. cor. of sec. 29, determined at the reported bearing and from the witness cor. established by Johnstone, in 1986, and is accepted for the cor., and is accepted for the cor., monumented with a steel reinforcing rod, 5/8" dia., firmly set, projecting 2" above ground, from which bearing trees mkd. by Johnstone

    A fir, 42" dia., bears S.7¼°E., 31.5 ft., with a healed blaze.

    A cedar, 23" dia., bears N.61¾°W., 20.8 ft., with fragmentary scribe marks visible on an open blaze.

At the corner point

Drive an iron rod, 6" long, 5/8" dia., 6" into a wooden bridge timber, with aluminum cap mkd.

T28S R4W

C ¼ S29

2014

Corner is located on a wooden bridge, on line with fences extending E. and S.

continued next page

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 240240

PRIMARY CORNER DESCRIPTION Center ¼ for section 29.

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ken Hoffine - For: Lone Rock Timberland Co - 7/2017 - M173-47  
-----

Condition report

Found - 2014 BLM aluminum cap  
42" D.Fir found at 2014 record S.7¼°E., 31.5'.  
Healed face and tag.  
Record 5/8" iron reference rod with aluminum cap  
found at 1986 record south 22.0'.  
Record 23" cedar is down has been washed out by  
action of Frozen Creek and is now out of  
position. (2014 record N.61¼°W., 20.8').  
We are unable to locate record 1986 fence corner at  
S.25°14'W., 53.0'.

Corner position lies in Frozen Creek. The 2014 BLM aluminum  
cap is set in a bridge deck on the north edge of the south  
running plank.