

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33 of T27-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 12 Page 5046-7)

Set post cor. to secs. 32 and 33, from which
A B.Oak 8" dia. bears S.55°E., 35 lks. dist.
A Laurel 12" dia. bears N.60°E., 50 lks. dist.
A Laurel 10" dia. bears N.40°W., 31 lks. dist.
A Laurel 15" dia. bears S.57°W., 69 lks. dist.

GLO Survey by W.H. Byars, Deputy Surveyor under Contract #
376 dated January 22, 1881 (DCSO records, Volume 12 Pg. 5079)

Set new post as per instructions.
Bearing trees all standing, viz:
A B.Oak 8" dia. bears S.55°E., 35 lks. dist.
A Laurel 12" dia. bears N.60°E., 50 lks. dist.
A Laurel 10" dia. bears N.40°W., 31 lks. dist.
A Laurel 15" dia. bears S.57°W., 69 lks. dist.

F.C. Frear, D.C.S. Wit: Ingram & Adams, Dec. 11-13 1918
Volume 3 Page 45 and C.S. File 4/34

Renewed from old Gov't BTs. Set 3/4" x 30" Galv. I.P. from
which, All old gov. trees, remarked, still stand except
the Black Oak.

James W. Byron, Deputy - M. Godfrey; S.A. Bilow - January 23,
1959 - C.S. File 49/130-11

Found - 3/4" Iron pipe set by Frear.
Also part of base of old Laurel that checks bearing
and dist. for orig. SW BT, center burned, no
scribing found.
No other orig. BTs found. This area burned last
year.

Set brass cap alongside of iron pipe mkd: County Surveyors Off
1959

S 32 | S33 T27S
S 5 | S 4 T28S R4W

New BTs - 12" Cedar bears S.53½°W., 99.9 ft. scribed S 5
T28S R4W CS BT.
34" R.Fir bears N.79°W., 37.0 ft. scribed S32 T27S
R4W CS BT.

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33 of T27-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

8" R.Fir bears S.56½°E., 75.4 ft. scribed S 4 T28S
R4W CS BT.
8" Cedar bears N.44½°E., 118.5 ft. scribed S33 T27S
R4W CS BT.

Milo E. Godfrey, Deputy Co. Surveyor; Wm. Stoffel; M.Stone
M. Darby - April/May 1964 - C.S. File 53/33-69

Found - Brass cap set in 1959. Also ½" I.Pipe.
3 BTs mkd. in 1959 still in good condition:
12" I.Cedar S.53½°W., 99.9 ft.
34" D.Fir N.79°W., 37.0 ft.
8" D.Fir S.56½°E., 75.4 ft.
NE tree is now broken off.
New BT - 8" D.Fir N.58°E., 100.4 ft. mkd: T27S R4W S33 CSBT.

Found 1959 Brass cap and 6 BTs. BLM Cadastral survey by
Lynn Roseberry, under Group #636, May/June 1967. (DCSO
records, Volume 34 Pages 14191-92)

Found 1959 brass cap and 5 BTs. BLM Cadastral survey by
James Jelley under Group #700, April 1970. (DCSO records
Volume 35 Page 14463)