

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5633)

Set fir post for 1/4 cor., from which:
 Cedar, 12" dia., bears S.75°W., 21 lks.
 Laurel, 12" dia., bears N.68°W., 19 lks.

BLM resurvey by Zirpel and Glenn, under Special Instructions dated August 29, 1957 (DCSO records, Vol. 29 Page 12250)

The 1/4 cor. for secs. 21 & 28, determined at record bearing and distance from the remains of the original bearing trees, as follows:

- A rotted madrone stump, 16" dia., bears N.68°W., 19 lks., no scribe marks visible.
- A sawed cedar stump, 25" dia., bears S.75°W., 21 lks., with scribe marks 1/4S visible on opened blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap marked:

	T28S	R4W
	1/4	<u>S 21</u>
		S 28
		1958

from which
 A fir, 21" dia., bears N.31 1/4°W., 84 1/2 lks., mkd: 1/4 S21 BT.
 A Fir, 5' dia., bears S.7°45'W., 70 lks., mkd: 1/4 S 21 BT.

Fd. Ok by R. Brown, M 116-52 - 1/93

Ken Hoffine - For: Lone Rock Timber Co. - 5/14/2013 - C.S. File 65/78-43

Found - 1958 BLM Cap at ground level, (properly mkd)
 26" D.Fir bears N.31 1/4°W., 55.77 ft. as per record healed face and tag
 Rotten remains of D.Fir bears S.7 3/4°W., 46.2 ft. as per record no marks found

New - 14" D.Fir bears S.59°E., 16.9 ft. We scribe 1/4 S28 BT and nail aluminum bearing tree tag to the tree.

Note - Corner lies on steep southwest slope. We have reblazed property lines to the south and west with red property line and flo blue flagging, and painted blazes with flo red paint.