

PRIMARY CORNER DESCRIPTION 1/4 Corner for Sections 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract #376 dated Jan. 22, 1881. (DCSO records Vol. 13 Page(s) 5634-45)

Set Chinkapin post for 1/4 sec. cor. from which:
A Fir, 72" dia. bears N.30°E., 23 lks.
A Fir, 60" dia. bears S.45°W., 45 lks.

BLM resurvey by Zirpel and Glenn under Special Instructions dated Aug. 29, 1957 (DCSO records Vol. 29 Page(s) 12253-54)

The 1/4 sec. cor. of secs. 9 and 16, determined at record distance from the remains of the original bearing trees, as follows:

A sawed and burned fir stump, 72" dia. bears N.28½°E., 23 lks. dist., with faint and illegible scribe marks visible. (rec. bearing N.30°E.)

A broken-off fir snag, 60" dia. bears S.54°W., 45 lks. dist. with axe marks visible. (rec. bearing S.45°W)

Set - at the corner point set an iron post, 28" long, 2½" dia. 24" in the ground, with brass cap marked:

T28S R4W

¼ $\frac{S\ 9}{S\ 16}$
1958

from which:

A white fir, 8" dia. bears N.32°W., 35 3/4 lks dist., marked ¼ S9 BT.

A white fir, 15" dia. bears S.43°45'W., 96 lks. dist., marked ¼ S16 BT.

David Edwards - For: Seneca Jones Tbr Co - 4/2010 - M 160-56

Found - Brass cap
Previous BTs gone.

New BTs- 7" dia. fir bears N.9°E., 4.65 ft. scribed "¼ S9 BT"
9" dia. fir bears S.5°E., 9.75 ft scribed "¼ S16 BT"
6 ft. steel post set 2' east.